



CORPORATION OF THE TOWNSHIP OF ESQUIMALT

Municipal Hall
1229 Esquimalt Road
Esquimalt, B.C. V9A 3P1

Legislation Details (With Text)

File #: 17-161 **Version:** 1 **Name:**
Type: Staff Report **Status:** Passed
File created: 4/18/2017 **In control:** Council
On agenda: 4/24/2017 **Final action:** 4/24/2017
Title: Traffic Order 1243 - McAdam Place and Parklands Drive, Staff Report EPW-17-013
Sponsors:
Indexes:
Code sections:
Attachments: 1. Attachment A - Traffic Order 1243

Date	Ver.	Action By	Action	Result
4/24/2017	1	Council	approved	Pass

REQUEST FOR DECISION

DATE: April 24, 2017 Report No. EPW-17-013
TO: Laurie Hurst, Chief Administrative Officer
FROM: Jeff Miller, Director of Engineering and Public Works

SUBJECT:
Implementation of Traffic Control Review Project Recommendations - Traffic Order 1243

RECOMMENDATION:

That Council approve Traffic Order 1243 that "Stop" sign and road markings be installed on McAdam Place at the intersection of Parklands Drive.

RELEVANT POLICY:

Streets and Traffic Regulation Bylaw, 2005, No. 2607

STRATEGIC RELEVANCE:

Healthy and Liveable Community - ensure multi-modal traffic strategies consider and reflect business and residential growth and development

Well Managed and Maintained Infrastructure - identify infrastructure repair and proactively plan for replacement needs

BACKGROUND:

In early 2016, the Township received a Traffic Control Review Report (Staff Report EPW-16-001). This Report was sponsored by ICBC and the Township with the work being completed by a

professional engineer/traffic engineer with an external consultant. The objective of the Project was to undertake a comprehensive review of traffic signs and road markings within the Township of Esquimalt.

The location in question is the intersection of McAdam Place and Parklands Drive. This is a four legged intersection with no traffic controls on McAdam Place and Parklands Drive legs. However it does have traffic control on the west leg that services a strata property. It was identified to have a high priority for action in the Report. The recommendation is that a stop sign and road markings be installed on McAdam Place. See Attachment A for location map and Traffic Order.

ISSUES:

1. Rationale for Selected Option

The four leg intersection of McAdam Place at Parklands Drive is currently uncontrolled except for the west leg that services the strata subdivision. This can lead drivers traveling on the municipal roads directions to assume that they have the right of way in the intersection. This assumption also invites drivers to operate vehicles at higher speeds through the intersections. At this location, due to the surrounding streetscape, foliage and buildings, sight lines are reduced for a driver which diminishes a driver's ability to observe and react to other vehicles and pedestrians.

The Report's recommendation and Staff's opinion is the addition of a stop sign on the McAdam Place leg of the intersection is the appropriate traffic control for this location. This will provide traffic control on the minor leg of the intersection and will match the other minor leg to the strata subdivision. It is anticipated that the addition of the stop sign at this intersection will provide drivers with visual information as to who has the right of way, lower the speed of vehicles and thus increase the overall safety of the intersection.

2. Organizational Implications

The proposed Traffic Order would be prepared by Engineering and signed by the Corporate Officer and the Director of Engineering and Public Works. Public Works would then install the stop signage and road markings on McAdam Place. The Traffic Order would also be forwarded to Victoria Police Department (Vic PD). These activities will not impose any significant organizational implications.

3. Financial Implications

The Traffic Order and implementation can be accommodated within the current operational budgets for the various departments that will be involved in the issuing of the Traffic Order.

4. Sustainability & Environmental Implications

There are no sustainability or environmental implications to the Traffic Order. An increased level of safety will be achieved due to the traffic control.

5. Communication & Engagement

Once a traffic order has been approved, this information will be posted to the Township's website

and other social media forums. At the locations “new” tabs will be installed on the traffic control devices where it is appropriate. These tabs will remain for approximately 6 months to assist residents adjust to the new traffic control devices. The change in traffic control would also be forwarded to Vic PD.

ALTERNATIVES:

1. That Council approve Traffic Order 1243 that “Stop” sign and road markings be installed on McAdam Place at the intersection of Parklands Drive.
2. That Council not approve Traffic Order 1243 that “Stop” sign and road markings be installed on McAdam Place at the intersection of Parklands Drive.